

New Trim-pot´s for the Drake R-7

R1808: In my R7, the AF had sometimes a cracking noise. The reason was a small flutter of the stabilised 13,8VDC-supply. The variations where only about 100mV, but enough to be heard in the speaker. The reason was a intermittent trim-pot (R1808) on the 13,8VDC regulator board, which caused the flutter. This pot had to be exchanged.

R1903: Additionally R1903 (looked bad) on the power supply board was replaced as a precaution by a 10-gear pot. The pin-configuration of this new pot was different from the old pot, so the pcb had to be modified a little bit.

The pictures tell more than thousand words.....DON'T FORGET REALIGNMENT !



If you want to contact the author:
Stefan Steger, DL7MAJ, eMail: dl7maj@darcl.de
Homepage: www.dl7maj.de

•-•• ••-•